

February 21, 2024

Ms. Brooke Snow
Village of Algonquin
110 Meyer Drive
Algonquin, Illinois 60102

**Subject: Pre-Demolition Asbestos-Containing Material Survey
Former Creekside Tap
7 South Main Street, Algonquin, Illinois 60102
True North Project No. T243001**

Dear Ms. Snow:

True North Consultants, Inc. (True North) was retained by the Village of Algonquin (Client) to conduct a pre-demolition asbestos-containing material survey of the former Creekside Tap located at 7 South Main Street in Algonquin, Illinois (Site). Survey services were provided by an Illinois Department of Public Health (IDPH) licensed Asbestos Building Inspector (Mark Dreher – License No. 100-19959) on February 15, 2024.

The purpose of the survey was to determine the asbestos content of suspect asbestos-containing materials associated with the structure prior to planned demolition activities at the Site. A total of sixty-five (65) bulk samples (including mastics and multiple sample layers) were analyzed for asbestos content. The bulk samples were submitted to a National Institute of Standards and Technology (NIST), National Voluntary Laboratory Accreditation Program (NVLAP) accredited laboratory for analysis (Eurofins CEI, Inc. – Accreditation No. 101768-0).

The bulk samples were analyzed for asbestos content in accordance with the procedures for Polarized Light Microscopy (PLM) with dispersion staining, contained in the Environmental Protection Agency (EPA) *Method for the Determination of Asbestos in Bulk Building Materials* (EPA/600/R-93/116). Results of sample analysis were reported as a percent composition. The following is a summary of PLM analytical results for sampled materials:

Summary of Findings: Suspect Asbestos-Containing Materials				
Material Description	Sample Number(s)	Location(s)	Estimated Quantity	Asbestos Content
Double Layer Floor Tile with Black Mastic (Beige 12"x12" Floor Tile over 9"x9" Floor Tile)	MFA-1,2,3	Located beneath plank flooring in the main seating area of the bar (located on wood subflooring).	575 Square Feet	Top Layer Floor Tile: None Detected Top Layer Mastic: None Detected Bottom Layer Floor Tile: None Detected Bottom Layer Mastic: 5% Chrysotile
12" x 24" Vinyl Flooring with Yellow Mastic – Dark Gray	MFB-1,2,3	Located behind the bar area and bar bathrooms.	125 Square Feet	None Detected



Summary of Findings: Suspect Asbestos-Containing Materials

Material Description	Sample Number(s)	Location(s)	Estimated Quantity	Asbestos Content
12" x 12" Floor Tile with Black & Brown Mastics and Vapor Barrier – Light Gray	MFC-1,2,3	Located beneath plank flooring in the bar storage area immediately southeast of bar (located on wood subflooring).	100 Square Feet	Floor Tile: 3% Chrysotile Mastics: None Detected Vapor Barrier: None Detected
Double Layer Floor Tile with Mastic – Brown	MFD-1,2,3	Located in the 1 st level walk-in cooler room, immediately adjacent to cooler.	30 Square Feet	None Detected
Sheet Flooring with Brown Mastic	MFE-1,2,3	Located beneath carpet and partially beneath double layer flooring within the 1 st level walk-in cooler room (located on wood subflooring).	125 Square Feet	Sheet Flooring: 20% Chrysotile Mastic: 3% Chrysotile
12" x 12" Floor Tile with Black Mastic – Gray / Beige Mottled	MFF-1,2,3	Located beneath tongue-&-groove flooring and plywood flooring throughout the central apartment (located on wood subflooring).	275 Square Feet	Floor Tile: None Detected Mastic: 3% Chrysotile
9" x 9" Floor Tile with Black Mastic – Brown	MFG-1,2,3	Located beneath carpet in the living room of the far southeast apartment (located on wood subflooring).	115 Square Feet	Floor Tile: 7% Chrysotile Mastic: 5% Chrysotile
9" x 9" Floor Tile with Black Mastic – White	MFH-1,2,3	Located beneath carpet in the bedroom of the far southeast apartment (located on wood subflooring).	100 Square Feet	Floor Tile: 7% Chrysotile Mastic: 5% Chrysotile
Drywall & Joint Compound	MDA-1,2,3	Located throughout the southeast half of the structure on walls and ceilings.	3,000 Square Feet	None Detected
Wall Paneling Adhesive – Brown	MMA-1,2,3	Located behind wood wall paneling throughout the bar area.	425 Square Feet	None Detected
White Coating Material on Walls & Ceilings	MMB-1,2,3	Located on walls and ceilings throughout the bar area.	1,300 Square Feet	None Detected
Perimeter Wall Vapor Barrier – Black	MMC-1,2,3	Located between exterior siding and interior wallboards along the perimeter walls of the bar area.	1,500 Square Feet	None Detected



Summary of Findings: Suspect Asbestos-Containing Materials				
Material Description	Sample Number(s)	Location(s)	Estimated Quantity	Asbestos Content
Walk-In Cooler Insulation – Cork & Vapor Barrier	MMD-1,2,3	Located in the 1 st floor cooler room near bar area.	200 Square Feet	None Detected
Wall Cavity Insulation	MME-1,2,3	Located within drywall wall cavities throughout the apartments.	1,500 Square Feet	None Detected
Pipe Insulation	TPA-1,2,3	Located in the northwest area of the basement on one pipe.	15 Linear Feet	65% Chrysotile
Mud Joint Fitting	TFA-1,2,3	Located in the northwest area of the basement on one pipe.	2 Fittings	50% Chrysotile
Roof Shingle System	MRA-1,2,3	Located on the roof of the structure.	2,500 Square Feet	None Detected

Table Notes:

- (1) The scope of sampling was limited to the aforementioned materials only. If additional suspect asbestos-containing materials are identified during planned demolition activities at the Site, additional testing may be required.
- (2) Any quantities of material identified within this report are solely intended to be estimates and are not intended to be exact.

The Environmental Protection Agency (EPA) defines asbestos-containing materials as those materials that contain greater than 1% asbestos. **Based upon the results of analysis, asbestos-containing materials were identified at the Site.** It should be noted that asbestos-containing flooring mastics were observed to be present on wood subfloors in areas identified above.

Due to the health effects associated with asbestos exposure, various federal, state, and local agencies have promulgated standards and regulations for the performance of asbestos related activities. Specifically, asbestos-containing materials at the Site may be regulated by the Occupational Safety and Health Administration (OSHA), Environmental Protection Agency (EPA), Illinois Department of Public Health (IDPH), and other local agencies.

In that asbestos-containing materials were identified at the Site, the aforementioned asbestos regulations apply to the removal or disturbance of these materials. The Illinois Environmental Protection Agency (IEPA) requires formal notification prior to structural demolition activities regardless of the presence or absence of asbestos-containing materials.



Enclosed with this letter are copies of laboratory analytical results and inspector credentials. If you have any questions regarding this report, or if we can be of further assistance, please contact us at your convenience.

Sincerely,

TRUE NORTH CONSULTANTS

Mark Dreher
Staff Consultant

Ryan LaDieu
Project Executive

Attachments: Attachment A – Laboratory Analytical Report
Attachment B – Asbestos Building Inspector Accreditations



ATTACHMENT A
Laboratory Analytical Report

February 21, 2024

True North Consultants, Inc.
1000 East Warrenville Road Suite 140
Naperville, IL 60563

CLIENT PROJECT: 7 S. Main Street, T243001
CEI LAB CODE: B243402


Dear Customer:

Enclosed are asbestos analysis results for PLM Bulk samples received at our laboratory on February 19, 2024. The samples were analyzed for asbestos using polarizing light microscopy (PLM) per the EPA 600 Method.

Sample results containing >1% asbestos are considered asbestos-containing materials (ACMs) per EPA regulatory requirements. The detection limit for the EPA 600 Method is <1% asbestos by weight as determined by visual estimation.

Thank you for your business and we look forward to continuing good relations.

Kind Regards,



Tianbao Bai, Ph.D., CIH
Laboratory Director



CEI

ASBESTOS ANALYTICAL REPORT

By: Polarized Light Microscopy

Prepared for

True North Consultants, Inc.

CLIENT PROJECT: 7 S. Main Street, T243001

LAB CODE: B243402

TEST METHOD: EPA 600 / R93 / 116 and EPA 600 / M4-82 / 020

REPORT DATE: 02/21/24

TOTAL SAMPLES ANALYZED: 41

SAMPLES >1% ASBESTOS: 11



CEI

Asbestos Report Summary

By: POLARIZING LIGHT MICROSCOPY

PROJECT: 7 S. Main Street, T243001

LAB CODE: B243402

METHOD: EPA 600 / R93 / 116 and EPA 600 / M4-82 / 020

Client ID	Layer	Lab ID	Color	Sample Description	ASBESTOS %
MFA-1		B243402.01A	Cream	Floor Tile	None Detected
		B243402.01B	Tan	Mastic	None Detected
		B243402.01C	Beige	Floor Tile	None Detected
		B243402.01D	Black	Mastic	Chrysotile 5%
MFA-2		B243402.02A	Cream	Floor Tile	None Detected
		B243402.02B	Tan	Mastic	None Detected
		B243402.02C	Beige	Floor Tile	None Detected
		B243402.02D		Sample Not Analyzed per COC	
MFA-3		B243402.03A	Cream	Floor Tile	None Detected
		B243402.03B	Tan	Mastic	None Detected
		B243402.03C	Beige	Floor Tile	None Detected
		B243402.03D		Sample Not Analyzed per COC	
MFB-1		B243402.04A	Gray,Patterned	Vinyl Flooring	None Detected
		B243402.04B	Tan	Mastic	None Detected
MFB-2		B243402.05A	Gray,Patterned	Vinyl Flooring	None Detected
		B243402.05B	Tan	Mastic	None Detected
MFB-3		B243402.06A	Gray,Patterned	Vinyl Flooring	None Detected
		B243402.06B	Tan	Mastic	None Detected
MFC-1		B243402.07A	Cream,Ptterned	Floor Tile	Chrysotile 3%
	Layer 1	B243402.07B	Tan	Mastic	None Detected
	Layer 2	B243402.07B	Black	Vapor Barrier	None Detected
	Layer 3	B243402.07B	Brown	Mastic	None Detected
MFC-2		B243402.08A		Sample Not Analyzed per COC	
	Layer 1	B243402.08B	Tan	Mastic	None Detected
	Layer 2	B243402.08B	Black	Vapor Barrier	None Detected
	Layer 3	B243402.08B	Brown	Mastic	None Detected
MFC-3		B243402.09A		Sample Not Analyzed per COC	
	Layer 1	B243402.09B	Tan	Mastic	None Detected
	Layer 2	B243402.09B	Black	Vapor Barrier	None Detected
	Layer 3	B243402.09B	Brown	Mastic	None Detected



CEI

Asbestos Report Summary

By: POLARIZING LIGHT MICROSCOPY

PROJECT: 7 S. Main Street, T243001

LAB CODE: B243402

METHOD: EPA 600 / R93 / 116 and EPA 600 / M4-82 / 020

Client ID	Layer	Lab ID	Color	Sample Description	ASBESTOS %
MFD-1		B243402.10A	Cream, Patterned	Floor Tile	None Detected
		B243402.10B	Tan	Mastic	None Detected
		B243402.10C	Blue	Floor Tile	None Detected
		B243402.10D	Clear	Mastic	None Detected
MFD-2		B243402.11A	Cream, Patterned	Floor Tile	None Detected
		B243402.11B	Tan	Mastic	None Detected
		B243402.11C	Blue	Floor Tile	None Detected
		B243402.11D	Clear	Mastic	None Detected
MFD-3		B243402.12A	Cream, Patterned	Floor Tile	None Detected
		B243402.12B	Tan	Mastic	None Detected
		B243402.12C	Blue	Floor Tile	None Detected
		B243402.12D	Clear	Mastic	None Detected
MFE-1		B243402.13A	Cream	Sheet Flooring	Chrysotile 20%
		B243402.13B	Brown	Mastic	Chrysotile 3%
MFE-2		B243402.14		Sample Not Analyzed per COC	
MFE-3		B243402.15		Sample Not Analyzed per COC	
MFF-1		B243402.16A	Beige,Patterned	Floor Tile	None Detected
		B243402.16B	Black	Mastic	Chrysotile 3%
MFF-2		B243402.17A	Beige,Patterned	Floor Tile	None Detected
		B243402.17B		Sample Not Analyzed per COC	
MFF-3		B243402.18A	Beige,Patterned	Floor Tile	None Detected
		B243402.18B		Sample Not Analyzed per COC	
MFG-1	Layer 1	B243402.19A	Tan	Mastic	None Detected
	Layer 2	B243402.19A	Tan	Floor Tile	Chrysotile 7%
		B243402.19B	Black	Mastic	Chrysotile 5%
MFG-2		B243402.20		Sample Not Analyzed per COC	
MFG-3		B243402.21		Sample Not Analyzed per COC	
MFH-1	Layer 1	B243402.22A	Tan	Mastic	None Detected
	Layer 2	B243402.22A	Tan	Floor Tile	Chrysotile 7%



CEI

Asbestos Report Summary

By: POLARIZING LIGHT MICROSCOPY

PROJECT: 7 S. Main Street, T243001

LAB CODE: B243402

METHOD: EPA 600 / R93 / 116 and EPA 600 / M4-82 / 020

Client ID	Layer	Lab ID	Color	Sample Description	ASBESTOS %
		B243402.22B	Black	Mastic	Chrysotile 5%
MFH-2		B243402.23		Sample Not Analyzed per COC	
MFH-3		B243402.24		Sample Not Analyzed per COC	
MDA-1		B243402.25	White	Drywall/Joint Compound	None Detected
MDA-2		B243402.26	White	Drywall/Joint Compound	None Detected
MDA-3		B243402.27	White	Drywall/Joint Compound	None Detected
MMA-1		B243402.28	Tan	Wall Panel Adhesive	None Detected
MMA-2		B243402.29	Tan	Wall Panel Adhesive	None Detected
MMA-3		B243402.30	Tan	Wall Panel Adhesive	None Detected
MMB-1		B243402.31	White,Cream	Coating Material	None Detected
MMB-2		B243402.32	White,Cream	Coating Material	None Detected
MMB-3		B243402.33	White,Cream	Coating Material	None Detected
MMC-1		B243402.34	Black	Wall Vapor Barrier	None Detected
MMC-2		B243402.35	Black	Wall Vapor Barrier	None Detected
MMC-3		B243402.36	Black	Wall Vapor Barrier	None Detected
MMD-1	Layer 1	B243402.37	Brown	Cooler Insulation (Cork)	None Detected
	Layer 2	B243402.37	Black	Cooler Insulation (Vapor Barrier)	None Detected
MMD-2	Layer 1	B243402.38	Brown	Cooler Insulation (Cork)	None Detected
	Layer 2	B243402.38	Black	Cooler Insulation (Vapor Barrier)	None Detected
MMD-3	Layer 1	B243402.39	Brown	Cooler Insulation (Cork)	None Detected
	Layer 2	B243402.39	Black	Cooler Insulation (Vapor Barrier)	None Detected
MME-1	Layer 1	B243402.40	Tan	Wall Insulation (Cellulose)	None Detected
	Layer 2	B243402.40	Black	Wall Insulation (Vapor Barrier)	None Detected
MME-2	Layer 1	B243402.41	Tan	Wall Insulation (Cellulose)	None Detected
	Layer 2	B243402.41	Black	Wall Insulation (Vapor Barrier)	None Detected
MME-3	Layer 1	B243402.42	Tan	Wall Insulation (Cellulose)	None Detected
	Layer 2	B243402.42	Black	Wall Insulation (Vapor Barrier)	None Detected
TPA-1		B243402.43	Cream	Pipe Insulation	Chrysotile 65%
TPA-2		B243402.44		Sample Not Analyzed per COC	
TPA-3		B243402.45		Sample Not Analyzed per COC	
TFA-1		B243402.46	White	Mud Joint Fittings	Chrysotile 50%



CEI

Asbestos Report Summary

By: POLARIZING LIGHT MICROSCOPY

PROJECT: 7 S. Main Street, T243001

LAB CODE: B243402

METHOD: EPA 600 / R93 / 116 and EPA 600 / M4-82 / 020

Client ID	Layer	Lab ID	Color	Sample Description	ASBESTOS %
TFA-2		B243402.47		Sample Not Analyzed per COC	
TFA-3		B243402.48		Sample Not Analyzed per COC	
MRA-1	Layer 1	B243402.49	Black	Roof Shingle	None Detected
	Layer 2	B243402.49	Gray	Roof Shingle	None Detected
MRA-2	Layer 1	B243402.50	Black	Roof Shingle	None Detected
	Layer 2	B243402.50	Gray	Roof Shingle	None Detected
MRA-3	Layer 1	B243402.51	Black	Roof Shingle	None Detected
	Layer 2	B243402.51	Gray	Roof Shingle	None Detected

ASBESTOS BULK ANALYSIS

By: POLARIZING LIGHT MICROSCOPY

Client: True North Consultants, Inc.
 1000 East Warrenville Road Suite 140
 Naperville, IL 60563

Lab Code: B243402
Date Received: 02-19-24
Date Analyzed: 02-20-24
Date Reported: 02-21-24

Project: 7 S. Main Street, T243001

ASBESTOS BULK PLM, EPA 600 METHOD

Client ID Lab ID	Lab Description	Lab Attributes	NON-ASBESTOS COMPONENTS				ASBESTOS %
			Fibrous		Non-Fibrous		
MFA-1 B243402.01A	Floor Tile	Homogeneous	2%	Cellulose	60%	Vinyl	None Detected
		Cream Fibrous Bound			38%	Calc Carb	
B243402.01B	Mastic	Homogeneous	2%	Cellulose	60%	Mastic	None Detected
		Tan Fibrous Bound			38%	Calc Carb	
B243402.01C	Floor Tile	Homogeneous	2%	Cellulose	60%	Vinyl	None Detected
		Beige Fibrous Bound			38%	Calc Carb	
B243402.01D	Mastic	Homogeneous	2%	Cellulose	60%	Mastic	5% Chrysotile
		Black Fibrous Bound			33%	Calc Carb	
MFA-2 B243402.02A	Floor Tile	Homogeneous	2%	Cellulose	60%	Vinyl	None Detected
		Cream Fibrous Bound			38%	Calc Carb	
B243402.02B	Mastic	Homogeneous	2%	Cellulose	60%	Mastic	None Detected
		Tan Fibrous Bound			38%	Calc Carb	
B243402.02C	Floor Tile	Homogeneous	2%	Cellulose	60%	Vinyl	None Detected
		Beige Fibrous Bound			38%	Calc Carb	
B243402.02D	Sample Not Analyzed per COC						

ASBESTOS BULK ANALYSIS

By: POLARIZING LIGHT MICROSCOPY

Client: True North Consultants, Inc.
 1000 East Warrenville Road Suite 140
 Naperville, IL 60563

Lab Code: B243402
Date Received: 02-19-24
Date Analyzed: 02-20-24
Date Reported: 02-21-24

Project: 7 S. Main Street, T243001

ASBESTOS BULK PLM, EPA 600 METHOD

Client ID Lab ID	Lab Description	Lab Attributes	NON-ASBESTOS COMPONENTS				ASBESTOS %
			Fibrous		Non-Fibrous		
MFA-3 B243402.03A	Floor Tile	Homogeneous	2%	Cellulose	60%	Vinyl	None Detected
		Cream Fibrous Bound			38%	Calc Carb	
B243402.03B	Mastic	Homogeneous	2%	Cellulose	60%	Mastic	None Detected
		Tan Fibrous Bound			38%	Calc Carb	
B243402.03C	Floor Tile	Homogeneous	2%	Cellulose	60%	Vinyl	None Detected
		Beige Fibrous Bound			38%	Calc Carb	
B243402.03D	Sample Not Analyzed per COC						
MFB-1 B243402.04A	Vinyl Flooring	Heterogeneous	2%	Cellulose	60%	Vinyl	None Detected
		Gray,Patterned Fibrous Bound			38%	Calc Carb	
B243402.04B	Mastic	Homogeneous	2%	Cellulose	60%	Mastic	None Detected
		Tan Fibrous Bound			38%	Calc Carb	
MFB-2 B243402.05A	Vinyl Flooring	Heterogeneous	2%	Cellulose	60%	Vinyl	None Detected
		Gray,Patterned Fibrous Bound			38%	Calc Carb	
B243402.05B	Mastic	Homogeneous	2%	Cellulose	60%	Mastic	None Detected
		Tan Fibrous Bound			38%	Calc Carb	

ASBESTOS BULK ANALYSIS

By: POLARIZING LIGHT MICROSCOPY

Client: True North Consultants, Inc.
 1000 East Warrenville Road Suite 140
 Naperville, IL 60563

Lab Code: B243402
Date Received: 02-19-24
Date Analyzed: 02-20-24
Date Reported: 02-21-24

Project: 7 S. Main Street, T243001

ASBESTOS BULK PLM, EPA 600 METHOD

Client ID Lab ID	Lab Description	Lab Attributes	NON-ASBESTOS COMPONENTS				ASBESTOS %
			Fibrous		Non-Fibrous		
MFB-3 B243402.06A	Vinyl Flooring	Heterogeneous Gray,Patterned Fibrous Bound	2%	Cellulose	60%	Vinyl Calc Carb	None Detected
B243402.06B	Mastic	Homogeneous Tan Fibrous Bound	2%	Cellulose	60%	Mastic Calc Carb	None Detected
MFC-1 B243402.07A	Floor Tile	Homogeneous Cream,Ptterned Fibrous Bound	2%	Cellulose	60%	Vinyl Calc Carb	3% Chrysotile
Layer 1 B243402.07B	Mastic	Homogeneous Tan Fibrous Bound	2%	Cellulose	60%	Mastic Calc Carb	None Detected
Layer 2 B243402.07B	Vapor Barrier	Homogeneous Black Fibrous Bound	65%	Cellulose	35%	Tar	None Detected
Layer 3 B243402.07B	Mastic	Homogeneous Brown Fibrous Bound	2%	Cellulose	60%	Mastic Calc Carb	None Detected
MFC-2 B243402.08A	Sample Not Analyzed per COC						
Layer 1 B243402.08B	Mastic	Homogeneous Tan Fibrous Bound	2%	Cellulose	60%	Mastic Calc Carb	None Detected

ASBESTOS BULK ANALYSIS

By: POLARIZING LIGHT MICROSCOPY

Client: True North Consultants, Inc.
 1000 East Warrenville Road Suite 140
 Naperville, IL 60563

Lab Code: B243402
Date Received: 02-19-24
Date Analyzed: 02-20-24
Date Reported: 02-21-24

Project: 7 S. Main Street, T243001

ASBESTOS BULK PLM, EPA 600 METHOD

Client ID Lab ID	Lab Description	Lab Attributes	NON-ASBESTOS COMPONENTS				ASBESTOS %
			Fibrous		Non-Fibrous		
Layer 2 B243402.08B	Vapor Barrier	Homogeneous Black Fibrous Bound	65%	Cellulose	35%	Tar	None Detected
Layer 3 B243402.08B	Mastic	Homogeneous Brown Fibrous Bound	2%	Cellulose	60%	Mastic 38% Calc Carb	None Detected
MFC-3 B243402.09A	Sample Not Analyzed per COC						
Layer 1 B243402.09B	Mastic	Homogeneous Tan Fibrous Bound	2%	Cellulose	60%	Mastic 38% Calc Carb	None Detected
Layer 2 B243402.09B	Vapor Barrier	Homogeneous Black Fibrous Bound	65%	Cellulose	35%	Tar	None Detected
Layer 3 B243402.09B	Mastic	Homogeneous Brown Fibrous Bound	2%	Cellulose	60%	Mastic 38% Calc Carb	None Detected
MFD-1 B243402.10A	Floor Tile	Heterogeneous Cream, Patterned Fibrous Bound	2%	Cellulose	60%	Vinyl 38% Calc Carb	None Detected
B243402.10B	Mastic	Homogeneous Tan Fibrous Bound	2%	Cellulose	60%	Mastic 38% Calc Carb	None Detected

ASBESTOS BULK ANALYSIS

By: POLARIZING LIGHT MICROSCOPY

Client: True North Consultants, Inc.
 1000 East Warrenville Road Suite 140
 Naperville, IL 60563

Lab Code: B243402
Date Received: 02-19-24
Date Analyzed: 02-20-24
Date Reported: 02-21-24

Project: 7 S. Main Street, T243001

ASBESTOS BULK PLM, EPA 600 METHOD

Client ID Lab ID	Lab Description	Lab Attributes	NON-ASBESTOS COMPONENTS				ASBESTOS %
			Fibrous		Non-Fibrous		
B243402.10C	Floor Tile	Homogeneous Blue Fibrous Bound	2%	Cellulose	60%	Vinyl 38% Calc Carb	None Detected
B243402.10D	Mastic	Homogeneous Clear Fibrous Bound	2%	Cellulose	60%	Mastic 38% Calc Carb	None Detected
MFD-2 B243402.11A	Floor Tile	Heterogeneous Cream,Patterned Fibrous Bound	2%	Cellulose	60%	Vinyl 38% Calc Carb	None Detected
B243402.11B	Mastic	Homogeneous Tan Fibrous Bound	2%	Cellulose	60%	Mastic 38% Calc Carb	None Detected
B243402.11C	Floor Tile	Homogeneous Blue Fibrous Bound	2%	Cellulose	60%	Vinyl 38% Calc Carb	None Detected
B243402.11D	Mastic	Homogeneous Clear Fibrous Bound	2%	Cellulose	60%	Mastic 38% Calc Carb	None Detected
MFD-3 B243402.12A	Floor Tile	Heterogeneous Cream,Patterned Fibrous Bound	2%	Cellulose	60%	Vinyl 38% Calc Carb	None Detected

ASBESTOS BULK ANALYSIS

By: POLARIZING LIGHT MICROSCOPY

Client: True North Consultants, Inc.
 1000 East Warrenville Road Suite 140
 Naperville, IL 60563

Lab Code: B243402
Date Received: 02-19-24
Date Analyzed: 02-20-24
Date Reported: 02-21-24

Project: 7 S. Main Street, T243001

ASBESTOS BULK PLM, EPA 600 METHOD

Client ID Lab ID	Lab Description	Lab Attributes	NON-ASBESTOS COMPONENTS				ASBESTOS %
			Fibrous		Non-Fibrous		
B243402.12B	Mastic	Homogeneous Tan Fibrous Bound	2%	Cellulose	60%	Mastic 38% Calc Carb	None Detected
B243402.12C	Floor Tile	Homogeneous Blue Fibrous Bound	2%	Cellulose	60%	Vinyl 38% Calc Carb	None Detected
B243402.12D	Mastic	Homogeneous Clear Fibrous Bound	2%	Cellulose	60%	Mastic 38% Calc Carb	None Detected
MFE-1 B243402.13A	Sheet Flooring	Heterogeneous Cream Fibrous Bound	15%	Cellulose	50%	Vinyl 15% Binder	20% Chrysotile
B243402.13B	Mastic	Homogeneous Brown Fibrous Bound	2%	Cellulose	60%	Mastic 35% Calc Carb	3% Chrysotile
Analyst opinion: Contamination from adjacent positive Sheet Flooring.							
MFE-2 B243402.14	Sample Not Analyzed per COC						
MFE-3 B243402.15	Sample Not Analyzed per COC						
MFF-1 B243402.16A	Floor Tile	Homogeneous Beige,Patterned Fibrous Bound	2%	Cellulose	60%	Vinyl 38% Calc Carb	None Detected

ASBESTOS BULK ANALYSIS

By: POLARIZING LIGHT MICROSCOPY

Client: True North Consultants, Inc.
 1000 East Warrenville Road Suite 140
 Naperville, IL 60563

Lab Code: B243402
Date Received: 02-19-24
Date Analyzed: 02-20-24
Date Reported: 02-21-24

Project: 7 S. Main Street, T243001

ASBESTOS BULK PLM, EPA 600 METHOD

Client ID Lab ID	Lab Description	Lab Attributes	NON-ASBESTOS COMPONENTS				ASBESTOS %
			Fibrous		Non-Fibrous		
B243402.16B	Mastic	Homogeneous Black Fibrous Bound	2%	Cellulose	60%	Mastic 35% Calc Carb	3% Chrysotile
MFF-2 B243402.17A	Floor Tile	Homogeneous Beige,Patterned Fibrous Bound	2%	Cellulose	60%	Vinyl 38% Calc Carb	None Detected
B243402.17B	Sample Not Analyzed per COC						
MFF-3 B243402.18A	Floor Tile	Homogeneous Beige,Patterned Fibrous Bound	2%	Cellulose	60%	Vinyl 38% Calc Carb	None Detected
B243402.18B	Sample Not Analyzed per COC						
MFG-1 Layer 1 B243402.19A	Mastic	Homogeneous Tan Fibrous Bound	2%	Cellulose	60%	Mastic 38% Calc Carb	None Detected
Layer 2 B243402.19A	Floor Tile	Homogeneous Tan Fibrous Bound	2%	Cellulose	60%	Vinyl 31% Calc Carb	7% Chrysotile
B243402.19B	Mastic	Homogeneous Black Fibrous Bound	2%	Cellulose	60%	Mastic 33% Calc Carb	5% Chrysotile
MFG-2 B243402.20	Sample Not Analyzed per COC						

ASBESTOS BULK ANALYSIS

By: POLARIZING LIGHT MICROSCOPY

Client: True North Consultants, Inc.
 1000 East Warrenville Road Suite 140
 Naperville, IL 60563

Lab Code: B243402
Date Received: 02-19-24
Date Analyzed: 02-20-24
Date Reported: 02-21-24

Project: 7 S. Main Street, T243001

ASBESTOS BULK PLM, EPA 600 METHOD

Client ID Lab ID	Lab Description	Lab Attributes	NON-ASBESTOS COMPONENTS				ASBESTOS %
			Fibrous		Non-Fibrous		
MFG-3 B243402.21	Sample Not Analyzed per COC						
MFH-1 Layer 1 B243402.22A	Mastic	Homogeneous Tan Fibrous Bound	2%	Cellulose	60%	Mastic 38% Calc Carb	None Detected
Layer 2 B243402.22A	Floor Tile	Homogeneous Tan Fibrous Bound	2%	Cellulose	60%	Vinyl 31% Calc Carb	7% Chrysotile
B243402.22B	Mastic	Homogeneous Black Fibrous Bound	2%	Cellulose	60%	Mastic 33% Calc Carb	5% Chrysotile
MFH-2 B243402.23	Sample Not Analyzed per COC						
MFH-3 B243402.24	Sample Not Analyzed per COC						
MDA-1 B243402.25	Drywall/Joint Compound	Heterogeneous White Fibrous Bound	10%	Cellulose	15%	Calc Carb 10% Binder 65% Gypsum	None Detected
MDA-2 B243402.26	Drywall/Joint Compound	Heterogeneous White Fibrous Bound	10%	Cellulose	15%	Calc Carb 10% Binder 65% Gypsum	None Detected
MDA-3 B243402.27	Drywall/Joint Compound	Heterogeneous White Fibrous Bound	10%	Cellulose	15%	Calc Carb 10% Binder 65% Gypsum	None Detected

ASBESTOS BULK ANALYSIS

By: POLARIZING LIGHT MICROSCOPY

Client: True North Consultants, Inc.
 1000 East Warrenville Road Suite 140
 Naperville, IL 60563

Lab Code: B243402
Date Received: 02-19-24
Date Analyzed: 02-20-24
Date Reported: 02-21-24

Project: 7 S. Main Street, T243001

ASBESTOS BULK PLM, EPA 600 METHOD

Client ID Lab ID	Lab Description	Lab Attributes	NON-ASBESTOS COMPONENTS				ASBESTOS %
			Fibrous		Non-Fibrous		
MMA-1 B243402.28	Wall Panel Adhesive	Homogeneous	2%	Cellulose	60%	Binder	None Detected
		Tan			38%	Calc Carb	
		Fibrous					
		Bound					
MMA-2 B243402.29	Wall Panel Adhesive	Homogeneous	2%	Cellulose	60%	Binder	None Detected
		Tan			38%	Calc Carb	
		Fibrous					
		Bound					
MMA-3 B243402.30	Wall Panel Adhesive	Homogeneous	2%	Cellulose	60%	Binder	None Detected
		Tan			38%	Calc Carb	
		Fibrous					
		Bound					
MMB-1 B243402.31	Coating Material	Heterogeneous	2%	Cellulose	73%	Calc Carb	None Detected
		White, Cream			10%	Binder	
		Fibrous			15%	Foam	
		Bound					
MMB-2 B243402.32	Coating Material	Heterogeneous	2%	Cellulose	73%	Calc Carb	None Detected
		White, Cream			10%	Binder	
		Fibrous			15%	Foam	
		Bound					
MMB-3 B243402.33	Coating Material	Heterogeneous	2%	Cellulose	73%	Calc Carb	None Detected
		White, Cream			10%	Binder	
		Fibrous			15%	Foam	
		Bound					
MMC-1 B243402.34	Wall Vapor Barrier	Homogeneous	65%	Cellulose	35%	Tar	None Detected
		Black					
		Fibrous					
		Bound					

ASBESTOS BULK ANALYSIS

By: POLARIZING LIGHT MICROSCOPY

Client: True North Consultants, Inc.
 1000 East Warrenville Road Suite 140
 Naperville, IL 60563

Lab Code: B243402
Date Received: 02-19-24
Date Analyzed: 02-20-24
Date Reported: 02-21-24

Project: 7 S. Main Street, T243001

ASBESTOS BULK PLM, EPA 600 METHOD

Client ID Lab ID	Lab Description	Lab Attributes	NON-ASBESTOS COMPONENTS				ASBESTOS %
			Fibrous		Non-Fibrous		
MMC-2 B243402.35	Wall Vapor Barrier	Homogeneous Black Fibrous Bound	65%	Cellulose	35%	Tar	None Detected
MMC-3 B243402.36	Wall Vapor Barrier	Homogeneous Black Fibrous Bound	65%	Cellulose	35%	Tar	None Detected
MMD-1 Layer 1 B243402.37	Cooler Insulation (Cork)	Homogeneous Brown Non-fibrous Bound			100%	Cork	None Detected
Layer 2 B243402.37	Cooler Insulation (Vapor Barrier)	Homogeneous Black Fibrous Bound	65%	Cellulose	35%	Tar	None Detected
MMD-2 Layer 1 B243402.38	Cooler Insulation (Cork)	Homogeneous Brown Non-fibrous Bound			100%	Cork	None Detected
Layer 2 B243402.38	Cooler Insulation (Vapor Barrier)	Homogeneous Black Fibrous Bound	65%	Cellulose	35%	Tar	None Detected
MMD-3 Layer 1 B243402.39	Cooler Insulation (Cork)	Homogeneous Brown Non-fibrous Bound			100%	Cork	None Detected

ASBESTOS BULK ANALYSIS

By: POLARIZING LIGHT MICROSCOPY

Client: True North Consultants, Inc.
 1000 East Warrenville Road Suite 140
 Naperville, IL 60563

Lab Code: B243402
Date Received: 02-19-24
Date Analyzed: 02-20-24
Date Reported: 02-21-24

Project: 7 S. Main Street, T243001

ASBESTOS BULK PLM, EPA 600 METHOD

Client ID Lab ID	Lab Description	Lab Attributes	NON-ASBESTOS COMPONENTS			ASBESTOS %	
			Fibrous	Non-Fibrous			
Layer 2 B243402.39	Cooler Insulation (Vapor Barrier)	Homogeneous Black Fibrous Bound	65%	Cellulose	35%	Tar	None Detected
MME-1 Layer 1 B243402.40	Wall Insulation (Cellulose)	Homogeneous Tan Fibrous Loose	100%	Cellulose			None Detected
Layer 2 B243402.40	Wall Insulation (Vapor Barrier)	Homogeneous Black Fibrous Bound	65%	Cellulose	35%	Tar	None Detected
MME-2 Layer 1 B243402.41	Wall Insulation (Cellulose)	Homogeneous Tan Fibrous Loose	100%	Cellulose			None Detected
Layer 2 B243402.41	Wall Insulation (Vapor Barrier)	Homogeneous Black Fibrous Bound	65%	Cellulose	35%	Tar	None Detected
MME-3 Layer 1 B243402.42	Wall Insulation (Cellulose)	Homogeneous Tan Fibrous Loose	100%	Cellulose			None Detected
Layer 2 B243402.42	Wall Insulation (Vapor Barrier)	Homogeneous Black Fibrous Bound	65%	Cellulose	35%	Tar	None Detected



CEI

ASBESTOS BULK ANALYSIS

By: POLARIZING LIGHT MICROSCOPY

Client: True North Consultants, Inc.
1000 East Warrenville Road Suite 140
Naperville, IL 60563

Lab Code: B243402
Date Received: 02-19-24
Date Analyzed: 02-20-24
Date Reported: 02-21-24

Project: 7 S. Main Street, T243001

ASBESTOS BULK PLM, EPA 600 METHOD

Client ID Lab ID	Lab Description	Lab Attributes	NON-ASBESTOS COMPONENTS				ASBESTOS %
			Fibrous		Non-Fibrous		
TPA-1 B243402.43	Pipe Insulation	Homogeneous Cream Fibrous Loosely Bound	15%	Cellulose	20%	Binder	65% Chrysotile
TPA-2 B243402.44	Sample Not Analyzed per COC						
TPA-3 B243402.45	Sample Not Analyzed per COC						
TFA-1 B243402.46	Mud Joint Fittings	Homogeneous White Fibrous Loosely Bound	20%	Cellulose	30%	Binder	50% Chrysotile
TFA-2 B243402.47	Sample Not Analyzed per COC						
TFA-3 B243402.48	Sample Not Analyzed per COC						
MRA-1 Layer 1 B243402.49	Roof Shingle	Heterogeneous Black Fibrous Bound	25%	Fiberglass	10%	Gravel 60% Tar 5% Silicates	None Detected
MRA-1 Layer 2 B243402.49	Roof Shingle	Heterogeneous Gray Fibrous Bound	25%	Fiberglass	10%	Gravel 60% Tar 5% Silicates	None Detected
MRA-2 Layer 1 B243402.50	Roof Shingle	Heterogeneous Black Fibrous Bound	25%	Fiberglass	10%	Gravel 60% Tar 5% Silicates	None Detected

ASBESTOS BULK ANALYSIS

By: POLARIZING LIGHT MICROSCOPY

Client: True North Consultants, Inc.
1000 East Warrenville Road Suite 140
Naperville, IL 60563

Lab Code: B243402
Date Received: 02-19-24
Date Analyzed: 02-20-24
Date Reported: 02-21-24

Project: 7 S. Main Street, T243001

ASBESTOS BULK PLM, EPA 600 METHOD

Client ID Lab ID	Lab Description	Lab Attributes	NON-ASBESTOS COMPONENTS				ASBESTOS %
			Fibrous		Non-Fibrous		
Layer 2 B243402.50	Roof Shingle	Heterogeneous Gray Fibrous Bound	25%	Fiberglass	10%	Gravel Tar Silicates	None Detected
MRA-3 Layer 1 B243402.51	Roof Shingle	Heterogeneous Black Fibrous Bound	25%	Fiberglass	10%	Gravel Tar Silicates	None Detected
Layer 2 B243402.51	Roof Shingle	Heterogeneous Gray Fibrous Bound	25%	Fiberglass	10%	Gravel Tar Silicates	None Detected

LEGEND: Non-Anth = Non-Asbestiform Anthophyllite
Non-Trem = Non-Asbestiform Tremolite
Calc Carb = Calcium Carbonate

METHOD: EPA 600 / R93 / 116 and EPA 600 / M4-82 / 020

REPORTING LIMIT: <1% by visual estimation

REPORTING LIMIT FOR POINT COUNTS: 0.25% by 400 Points or 0.1% by 1,000 Points

REGULATORY LIMIT: >1% by weight

Due to the limitations of the EPA 600 method, nonfriable organically bound materials (NOBs) such as vinyl floor tiles can be difficult to analyze via polarized light microscopy (PLM). EPA recommends that all NOBs analyzed by PLM, and found not to contain asbestos, be further analyzed by Transmission Electron Microscopy (TEM). Please note that PLM analysis of dust and soil samples for asbestos is not covered under NVLAP accreditation. *Estimated measurement of uncertainty is available on request.*


This report relates only to the samples tested or analyzed and may not be reproduced, except in full, without written approval by Eurofins CEI. Eurofins CEI makes no warranty representation regarding the accuracy of client submitted information in preparing and presenting analytical results. Interpretation of the analytical results is the sole responsibility of the client. Samples were received in acceptable condition unless otherwise noted. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. Government.

Information provided by customer includes customer sample ID and sample description.

ANALYST:


Shilpa Ladekar

APPROVED BY:


Tianbao Bai, Ph.D., CIH
Laboratory Director



CEI

CHAIN OF CUSTODY

51

730 SE Maynard Road, Cary, NC 27511
 Tel: 866-481-1412; Fax: 919-481-1442

ECEI Lab Code: B243402
 ECEI Lab I.D. Range:

COMPANY INFORMATION	PROJECT INFORMATION
ECEI CLIENT #:	Job Contact: Mark Dreher
Company: True North Consultants	Email / Tel: mdreher@consulttruenorth.com
Address: 1000 E. Warrenville Road, Suite 140	Project Name: <u>7 S. Main Street</u>
Naperville, IL 60563	Project ID#: <u>T243001</u>
Billing Email: ap@consulttruenorth.com	PO #:
Tel:	State of sample origin <u>IL</u>

ECEI standard terms are Net 30 days

IF TAT IS NOT MARKED STANDARD 3 DAY TAT APPLIES.

ASBESTOS	METHOD	TURN AROUND TIME					
		4 HR	8 HR	1 DAY	2 DAY	3 DAY	5 DAY
PLM BULK	EPA 600/R-93/116	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
PLM POINT COUNT (400)	EPA 600/R-93/116	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
PLM POINT COUNT (1000)	EPA 600/R-93/116	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
PLM GRAV w POINT COUNT	EPA 600/R-93/116	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
PLM BULK	CARB 435	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
PCM AIR*	NIOSH 7400	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
TEM AIR	EPA AHERA	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
TEM AIR	NIOSH 7402	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
TEM AIR (PCME)	ISO 10312	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
TEM AIR	ASTM 6281-15	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
TEM BULK	CHATFIELD / EPA 600/R-93/116 Sec. 2.5.5.1	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
TEM DUST WIPE	ASTM D6480-19	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
TEM DUST MICROVAC	ASTM D5755-09 (2014)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
TEM SOIL	ASTM D7521-16	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
TEM VERMICULITE	CINCINNATI METHOD	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
TEM QUALITATIVE	IN-HOUSE METHOD	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
OTHER:		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

*Blanks should be taken from the same sample lot as field samples.

REMARKS / SPECIAL INSTRUCTIONS:		<input checked="" type="checkbox"/> Accept Samples <input type="checkbox"/> Reject Samples	
<u>Stop @ First Positive</u>			
Relinquished By:	Date/Time	Received By:	Date/Time
<u>[Signature]</u>	<u>2/16/2024</u>	<u>[Signature]</u>	<u>02/19/24 9:30</u>

By submitting samples, you are agreeing to ECEI's Terms and Conditions.
 Samples will be disposed of 30 days after analysis

81815032 0045

COMPANY CONTACT INFORMATION

Company:	Job Contact:
Project Name:	
Project ID #:	Tel:

SAMPLE ID#	DESCRIPTION / LOCATION	VOLUME/ AREA	TEST			
			PLM	<input type="checkbox"/>	TEM	<input type="checkbox"/>
T MFA-1,2,3	Double Layer Floor Tile w/ Black Mastic		PLM	<input checked="" type="checkbox"/>	TEM	<input type="checkbox"/>
MFB-1,2,3	12x24 Vinyl Flooring w/ Yellow Mastic		PLM	<input type="checkbox"/>	TEM	<input type="checkbox"/>
L MFC-1,2,3	12x12 Floor Tile w/ Black mastic + Vapor Barrier		PLM	<input type="checkbox"/>	TEM	<input type="checkbox"/>
T MFD-1,2,3	Double Layer Floor Tile w/ Mastic		PLM	<input type="checkbox"/>	TEM	<input type="checkbox"/>
L MFE-1,2,3	Sheet Flooring w/ Brown Mastic		PLM	<input type="checkbox"/>	TEM	<input type="checkbox"/>
T MFF-1,2,3	12x12 Floor Tile w/ Black Mastic		PLM	<input type="checkbox"/>	TEM	<input type="checkbox"/>
MFG-1,2,3	9x9 Floor Tile w/ Black Mastic - Brown		PLM	<input type="checkbox"/>	TEM	<input type="checkbox"/>
L MFH-1,2,3	9x9 Floor Tile, w/ Black Mastic - White		PLM	<input type="checkbox"/>	TEM	<input type="checkbox"/>
			PLM	<input type="checkbox"/>	TEM	<input type="checkbox"/>
T MDA-1,2,3	Drywall + Joint Compound		PLM	<input type="checkbox"/>	TEM	<input type="checkbox"/>
			PLM	<input type="checkbox"/>	TEM	<input type="checkbox"/>
MMA-1,2,3	Wall Panel Adhesive - Brown		PLM	<input type="checkbox"/>	TEM	<input type="checkbox"/>
MMB-1,2,3	White Coating Material on walls/ceilings		PLM	<input type="checkbox"/>	TEM	<input type="checkbox"/>
L MML-1,2,3	Perimeter Wall Vapor Barrier - Black		PLM	<input type="checkbox"/>	TEM	<input type="checkbox"/>
T MMD-1,2,3	Cooler Insulation - Cork + Vapor Barrier		PLM	<input type="checkbox"/>	TEM	<input type="checkbox"/>
MME-1,2,3	Wall Insulation		PLM	<input type="checkbox"/>	TEM	<input type="checkbox"/>
			PLM	<input type="checkbox"/>	TEM	<input type="checkbox"/>
TPA-1,2,3	Pipe Insulation		PLM	<input type="checkbox"/>	TEM	<input type="checkbox"/>
TFA-1,2,3	Mud Joint Fitting		PLM	<input type="checkbox"/>	TEM	<input type="checkbox"/>
			PLM	<input type="checkbox"/>	TEM	<input type="checkbox"/>
51. L MRA-1,2,3	Roof Shingle System		PLM	<input type="checkbox"/>	TEM	<input type="checkbox"/>
			PLM	<input type="checkbox"/>	TEM	<input type="checkbox"/>
			PLM	<input type="checkbox"/>	TEM	<input type="checkbox"/>
			PLM	<input type="checkbox"/>	TEM	<input type="checkbox"/>
			PLM	<input type="checkbox"/>	TEM	<input type="checkbox"/>
			PLM	<input type="checkbox"/>	TEM	<input type="checkbox"/>
			PLM	<input type="checkbox"/>	TEM	<input type="checkbox"/>



ATTACHMENT B
Asbestos Building Inspector Accreditations



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

MARK DREHER
 5708 SPRINGSIDE AVE
 DOWNERS GROVE, IL 60516

4/5/2023



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 19959

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

 <p>ASBESTOS PROFESSIONAL LICENSE</p>			<p>ENDORSEMENTS</p> <p>INSPECTOR</p> <p>PROJECT MANAGER</p> <p>AIR SAMPLING PROFESSIONAL</p>	<p>TC EXPIRES</p> <p>2/10/2024</p> <p>2/11/2024</p>
<p>ID NUMBER</p> <p>100 - 19959</p>	<p>ISSUED</p> <p>4/5/2023</p>	<p>EXPIRES</p> <p>05/15/2024</p>	<p>Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.</p>	
<p>MARK DREHER 5708 SPRINGSIDE AVE DOWNERS GROVE, IL 60516 Environmental Health</p>				

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
 EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | www.otssafety.com

2024

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Mark Dreher

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. This course is accredited by the State of Wisconsin, Department of Health Services under ch. DHS 159, Wis. Admin. Code, The Illinois Department of Public Health and The Indiana Department of Environmental Management, under 326 IAC 18. Training was in accordance with requirements listed under EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Location: 7635 125th Ave.
Kenosha, WI 53142

Certificate Number: BIRWI2402090816

Course Date: 2/9/2024

Exam Date: 2/9/2024

Expiration Date: 2/9/2025

Issue Date: 2/9/2024

A handwritten signature in black ink, appearing to read 'Tyler Nicholson', is written over a horizontal line.

Tyler Nicholson, Authorized Signer

